### **SECOND QUARTER 2013**

### **GROUNDWATER MONITORING REPORT**

Former Mondo Chrome Facility 4933 Firestone Boulevard, South Gate, California 90280

> SCP No. 0760 Site ID No. 2043G00 Global ID No. SL2043G1564

> > July 10, 2013

Charles F. Lindeman REA II - 20251

SESSIONAL GEO

OF CALIFOR

Paul Lipinski CA Professional Geologist No. 3991

Submitted by:

Leymaster Environmental Consulting, LLC 5500 East Atherton Street, Suite 210 Long Beach, California 90815

www.leymaster.net
562-799-9866

# TABLE OF CONTENTS

1.0 INTRODUCTION	1
2.0 SITE BACKGROUND	1
3.0 REGIONAL GEOLOGY & HYDROGEOLOGY	2
3.1 REGIONAL HYDROGEOLOGY	
3.2 SITE HYDROGEOLOGY	3
4.0 GROUNDWATER MONITORING RESULTS	3
4.1 Groundwater Elevation Data	
4.2 SAMPLE COLLECTION	
4.4 DISCUSSION OF ANALYTICAL RESULT	
5.0 DISPOSAL OF INVESTIGATION DERIVED WASTES	
6.0 CONCLUSIONS & RECOMMENDATIONS	7
TABLES	
Well Construction Details	Table 1
Groundwater Elevations 1998-2013	Table 2
Summary of VOC Analytical Detections in Groundwater	Table 3
Summary of Metal Analytical Detections in Groundwater	Table 4
FIGURES	
Local Area Map	Figure 1
Site Plot Plan	Figure 2
Groundwater Contours – June 2013	Figure 3
TCE Iso-Concentrations – June 2013	Figure 4
Analytical Results for VOCs, Metals and Cyanide – June 2013	Figure 5
ATTACHMENTS	
Well Location and Elevation Survey Data	Attachment I
Well Sample Data Logs	Attachment II
Laboratory Report of Analytical Results (Groundwater) and Chain-of-Custody Record	Attachment III
Non-Hazardous Waste Manifest No. 010418, Laboratory Report of Analytical Results (IDW) & Chain-of-Custody Record	Attachment IV
ining now recount (is it) or chain of custody record	1 teachine 1 v

### LEYMASTER ENVIRONMENTAL CONSULTING, LLC

### SECOND QUARTER 2013 GROUNDWATER MONITORING REPORT

Former Mondo Chrome Facility
4933 Firestone Boulevard, South Gate, California 90280

SCP No. 0760 Site ID No. 2043G00 Global ID No. SL2043G1564

#### 1.0 INTRODUCTION

This Second Quarter 2013 Groundwater Monitoring Report details Leymaster Environmental Consulting, LLC's (LEC) activities, findings and conclusions with respect to monitoring six groundwater wells at the former Mondo Chrome Facility located at 4933 Firestone Boulevard, South Gate, California 90280 (Figure 1 – Local Area Map).

### 2.0 SITE BACKGROUND

The Former Mondo Chrome site is an approximately 1,800 square-foot, one-story facility that has historically been utilized for industrial purposes. Mondo Chrome leased and operated an ornamental electroplating facility at the site between 1986 and 1990 (Figure 2 – Site Plot Plan). In 1990, the Los Angeles County Department of Health Services, Hazardous Materials Control Program conducted an emergency response to a chrome-solution spill at the facility. Additional violations, including improper storage of hazardous materials, were noted at that time. Subsequent site investigations were conducted at the facility in 1992, 1994, 1996, 1998 and 2001.

Twenty-seven soil and groundwater borings were installed at 18 locations that were defined by the previous use and/or storage of hazardous materials at the Mondo Chrome facility. Groundwater samples were collected from on-site and off-site locations utilizing both hydropunch methods (borings B12, B13, B15 & B17) and groundwater monitoring wells (MW1 through MW6). Contaminants historically detected in groundwater included total chromium (up to 9,720 micrograms per liter [ $\mu$ g/l]), cadmium (up to 6  $\mu$ g/l), perchloroethene (PCE, up to 707  $\mu$ g/l) and trichloroethene (TCE, up to 1,000  $\mu$ g/l).

Additional background information and the investigative history of the site can be found at: http://geotracker.waterboards.ca.gov/profile\_report.asp?global\_id=SL2043G1564

Second Quarter 2013 Groundwater Monitoring Report 4933 Firestone Boulevard, South Gate, CA 90280 SCP No. 0760; Site ID No. 2043G00; Global ID No. SL2043G1564 June 10, 2013 Page 2 of 7

### 3.0 REGIONAL GEOLOGY & HYDROGEOLOGY

### 3.1 Regional Hydrogeology

According to information from the Department of Water Resources (DWR, 1961) contained in a Frey Environmental groundwater investigation work plan for the subject site (Frey, May 27, 2011), the Former Mondo Chrome site is located within the Central Basin Pressure Area of the Downey Plain which is a subgroup of the Coastal Plain of Los Angeles County. The Downey Plain is a depositional feature consisting of alluvial fans from the Los Angeles River and Rio Hondo-San Gabriel River Systems. The Central Basin Pressure Area is characterized by the presence of multiple aquitards, most notably the Bellflower aquiclude. The Bellflower aquiclude is comprised of low permeability silts and clays that separate near surface waters from deeper water-bearing zones. The Bellflower aquiclude is estimated to be approximately 65 feet beneath the subject site and has an approximate thickness of 60 feet in the area of the site.

The Gaspur aquifer of the Lakewood Formation is the water-bearing unit located beneath the Bellflower aquiclude at the subject site. The Lakewood Formation has multiple water-bearing units including the Artesia, Exposition, Gage and Gardena aquifers. The San Pedro Formation underlies the Lakewood Formation and has multiple water-bearing units including the Hollydale, Jefferson, Lynwood, Silverado and Sunnyside aquifers.

The reported groundwater flow direction at the site changed significantly during 2000 and 2001, switching from southeasterly (2000) to northwesterly (2001). In order to confirm that flow calculations were based on accurate data, the historic "top of casing" elevations for the three on-site monitoring wells (MW1, MW2 and MW3) was resurveyed on October 4, 2012 by a licensed surveyor, Pacific Land Consultants, Inc. The "top-of-casing" elevations obtained by PLC on October 4, 2012 are in general agreement with the site's historically reported "top-of-casing" elevations and the historic flow directions appear to be correct.

On May 22, 23 and 24, 2013, one down-gradient and two cross-gradient groundwater monitoring wells (MW4, MW5 & MW6) were installed off-site by Gregg Drilling and Testing (*Off-Site Groundwater Monitoring Well Installation Report*, LEC, July 9, 2013). These three wells were incorporated into the site's groundwater monitoring network effective this Second Quarter of 2013. Well construction details for the site's six wells can be found in Table 1 (Well Construction Details) following the text of this report. Monitoring well location and elevation survey data can be found in Attachment I.

Second Quarter 2013 Groundwater Monitoring Report 4933 Firestone Boulevard, South Gate, CA 90280 SCP No. 0760; Site ID No. 2043G00; Global ID No. SL2043G1564 June 10, 2013 Page 3 of 7

### 3.2 Site Hydrogeology

Based on data collected between 1998 and 2013 from three on-site groundwater monitoring wells, the depth to groundwater beneath the site has increased from approximately 40 feet below ground surface (bgs) to approximately 49 feet bgs. Based on depth-to-groundwater measurements for monitoring wells MW1, MW2 and MW3, since 2001, the groundwater flow direction has generally been to the north, varying slightly between the northwest and northeast.

Based on depth-to-groundwater measurements for monitoring wells MW1 through MW6, on June 21, 2013, groundwater beneath the site was flowing in a northeasterly direction at a gradient of approximately 0.003 feet per foot east of the subject site. A groundwater contour map for the site is contained in Figure 3 (Groundwater Contours - June 2013).

#### 4.0 GROUNDWATER MONITORING RESULTS

Groundwater sampling for the Second Quarter 2013 was conducted on June 21, 2013, by Mr. Charles F. Lindeman, under the supervision of Mr. Paul Lipinski, California Professional Geologist No. 3991.

#### 4.1 Groundwater Elevation Data

Prior to low-flow purging and sampling, depth-to-water was measured in each of the wells using a Solinst Interface Probe (No. 122-003656-1). The temperature, pH, conductivity, and turbidity were obtained at two-minute intervals during low-flow purging using a Horiba U-52 multi-parameter meter (No. LEC0409). Temperature and conductivity measurements were within 10% of each other, and the pH measurements were within 0.1 units of each other, following the removal of two to four liters from each of the wells. The measurements of these parameters on June 21, 2013, are shown on the Well Sampling Data Logs contained in Attachment II. Groundwater elevation data collected during the June 21, 2013, sampling event are presented in the table below.

#### **Groundwater Elevation Data for June 21, 2013**

Monitoring Well No.	Casing Elevation (feet above msl)	Depth to Groundwater (June 21, 2013)	2 <sup>nd</sup> Quarter 2013 Groundwater Elevation (feet above msl)
MW1	109.60	49.33'	60.27
MW2	109.53	48.98'	60.55
MW3	109.66	49.34'	60.32
MW4	109.19	49.51'	59.68

Monitoring Well No.	Casing Elevation (feet above msl)	Depth to Groundwater (June 21, 2013)	2 <sup>nd</sup> Quarter 2013 Groundwater Elevation (feet above msl)
MW5	110.53	50.56'	59.97
MW6	109.60	49.24'	60.36

A groundwater contour map for the site is contained in Figure 3 (Groundwater Contours - June 2013). A summary of historical groundwater elevations can be found in Table 2 (Groundwater Elevations 1998 - 2013) following the text of this report.

#### 4.2 Sample Collection

Groundwater samples were collected from each well by low-flow purging using dedicated Proactive M-T submersible pumps and dedicated LDPE tubing. The samples were collected into laboratory-supplied 40-ml VOAs and 1-liter poly containers, properly labeled and stored in an iced cooler for transportation to a State-certified laboratory. Standard Chain-of-Custody procedures were maintained on all samples. The Chain-of-Custody Record with a request for analysis was initiated in the field by LEC. Each time responsibility for custody of the samples changed, the receiving and relinquishing custodians signed the record and entered the date and time of transfer of the samples. The laboratory signed for the receipt of the samples and returned a copy of the Chain-of-Custody Record to LEC.

#### 4.3 Analytical Result

All samples were submitted to Cal Tech Environmental Laboratories, 6814 Rosecrans Avenue, Paramount, CA (CA-DHS ELAP No. 2424), and analyzed for volatile organic compounds (VOCs) by EPA Method 8260B, for cadmium, chromium, and nickel by EPA Method 6010B, for hexavalent chromium by EPA Method 7196A, and for cyanide by Method SM4500-CN-E. The analytical data for groundwater samples collected on June 21, 2013, are tabulated in the table below.

Analytical Results for Groundwater – June 21, 2013

Analyte	MW 1	MW 2	MW 3	MW4	MW5	MW6	CA MCL
ТСЕ	200	9.6	33	7	130	210	5 μg/l
РСЕ	30	7	18	ND<0.5	2.3	1.6	5 μg/l
c-1,2-DCE	96	16	14	2.8	16	55	6 μg/l
t-1,2-DCE	5.4	ND<0.5	ND<0.5	ND<0.5	ND<0.5	ND<0.5	10 μg/l
1,2,3-TCP	ND<1	ND<1	ND<1	ND<1	ND<1	ND<1	NE

Second Quarter 2013 Groundwater Monitoring Report 4933 Firestone Boulevard, South Gate, CA 90280 SCP No. 0760; Site ID No. 2043G00; Global ID No. SL2043G1564 June 10, 2013 Page 5 of 7

Analyte	MW 1	MW 2	MW 3	MW4	MW5	MW6	CA MCL
1,4-Dioxane	ND<2	ND<2	ND<2	ND<2	ND<2	ND<2	NE
Cadmium	ND<10	ND<10	ND<10	ND<10	ND<10	ND<10	5 μg/l
Chromium	ND<10	ND<10	ND<10	ND<10	ND<10	ND<10	5 μg/l
Hex Chrome	ND<10	ND<10	ND<10	ND<10	ND<10	ND<10	50 μg/l
Nickel	ND<10	ND<10	ND<10	ND<10	ND<10	ND<10	100 μg/l
Cyanide	ND<50	ND<50	ND<50	ND<50	ND<50	ND<50	150 μg/l

TCE = Trichloroethene c-1,2-DCE - cis-1,2-Dichloroethene PCE = Perchloroethene t-1,2-DCE = trans-1,2-Dichloroethene N/E - None Established 1,2,3-TCP = 1,2,3-Trichloropropane

All results in micrograms per Liter (µg/l)

MCL – Maximum Contaminant Level for drinking water

A summary of analytical data for previous rounds of groundwater sampling can be found in Table 3 (Summary of VOC Analytical Detections in Groundwater) and Table 4 (Summary of Metal Analytical Detections in Groundwater). The Laboratory Report of Analytical Results and Chain-of-Custody Record for groundwater samples collected on June 21, 2013 are contained in Attachment III.

TCE iso-concentration contours and the analytical results for all VOCs, metals and cyanide, based on groundwater samples collected on June 21, 2013, are depicted in Figure 4 (TCE Iso-Concentrations – June 2013) and Figure 5 (Analytical Results for VOCs, Metals and CN – June 2013), respectively.

### 4.4 Discussion of Analytical Result

PCE (30  $\mu$ g/l), TCE (200  $\mu$ g/l) and the degradation product cis-1,2-DCE (96  $\mu$ g/l) were detected in monitoring well MW1 (adjacent to the site's former clarifier) at levels exceeding their applicable Maximum Contaminant Levels (MCLs) for drinking water (see table above). Trans-1,2-DCE (5.4  $\mu$ g/l) was detected in MW1 at a level below its MCL. No other VOCs were detected in MW1.

Monitoring wells MW2 and MW3, located hydraulically cross-gradient to the south, contained concentrations of PCE (7  $\mu$ g/l and 18  $\mu$ g/l, respectively) TCE (9.6  $\mu$ g/l and 33  $\mu$ g/l, respectively) and cis-1,2-DCE (16  $\mu$ g/l and 14  $\mu$ g/l, respectively) at levels

Second Quarter 2013 Groundwater Monitoring Report 4933 Firestone Boulevard, South Gate, CA 90280 SCP No. 0760; Site ID No. 2043G00; Global ID No. SL2043G1564 June 10, 2013 Page 6 of 7

exceeding their MCLs for drinking water. No other VOCs were detected in MW2 or MW3.

Monitoring well MW4, located hydraulically up-gradient to the east, contained detectable concentrations of TCE (7  $\mu$ g/l) and cis-1,2-DCE (2.8  $\mu$ g/l). Only TCE exceed its MCL in MW4. No other VOCs were detected in MW4.

Monitoring well MW5, hydraulically cross-gradient to the north, contained concentrations of TCE (130  $\mu$ g/l) and cis-1,2-DCE (16  $\mu$ g/l) at levels exceeding their MCLs for drinking water. PCE (2.3  $\mu$ g/l) was detected in MW5 at a level below its MCL. No other VOCs were detected in MW5.

Monitoring well MW6, hydraulically down-gradient to the west, contained concentrations of TCE (210  $\mu$ g/l) and cis-1,2-DCE (55  $\mu$ g/l) at levels exceeding their MCLs for drinking water. PCE (2.3  $\mu$ g/l) was detected in MW6 at a level below its MCL. No other VOCs were detected in MW6.

The emergent chemicals 1,2,3-Trichloropropane and 1,4-Dioxane were not detected in any groundwater monitoring well. Other historic contaminants of concern (cadmium, chromium, hexavalent chromium, nickel, and cyanide), were not detected in any groundwater monitoring well.

#### 5.0 DISPOSAL OF INVESTIGATION DERIVED WASTES

The investigation-derived waste (IDW) purge water was transferred into a DOT-approved, 55-gallon drum along with other IDWs (well development water) generated during the installation of off-site monitoring wells MW4, MW5, and MW6 and stored on-site in a secured area. Laboratory analytical results indicate that the drum contains non-hazardous wastes. The Laboratory Report of Analytical Results and Chain-of-Custody Record for the IDW water are contained in Attachment III.

The drum of non-hazardous IDW water was transported by KM Industrial of Long Beach, CA (USEPA ID No. CAR000075622) for proper disposal at Crosby & Overton of Long Beach, CA (USEPA ID No. CAD028409019) under Non-Hazardous Waste Manifest No. 010418 (Attachment IV).

Second Quarter 2013 Groundwater Monitoring Report 4933 Firestone Boulevard, South Gate, CA 90280 SCP No. 0760; Site ID No. 2043G00; Global ID No. SL2043G1564 June 10, 2013 Page 7 of 7

### 6.0 CONCLUSIONS & RECOMMENDATIONS

Concentrations of PCE ( $\leq$ 30 µg/l), TCE ( $\leq$ 210 µg/l) and the degradation product cis-1,2-DCE ( $\leq$ 96 µg/l) continue to be detected in groundwater beneath the site at levels exceeding their MCLs for drinking water. Trans-1,2-DCE was detected only in MW1 (5.4 µg/l) at a level below its MCL of 10 µg/l. No other VOCS were detected in any monitoring wells. The shallow groundwater beneath the subject site is not a drinking water aquifer.

Cadmium, chromium, hexavalent chromium, nickel, cyanide, 1,2,3-TCP, and 1,4-Dioxane were not detected in any groundwater monitoring well during this Second Quarter 2013 monitoring event.

Monitoring wells MW1 through MW6 will be monitored on a semi-annual basis (May-June and November-December) and reports submitted to the Regional Board by July 15 and January 15, respectively.

I, Jack L. Bliss, do hereby declare, under penalty of perjury under the laws of the State of California, that I am the property manager for the property commonly known as 4933 Firestone Boulevard, South Gate, California, that I am authorized to attest to the veracity of the information contained in the report described herein, and that, to my knowledge based solely on the representation of Leymaster Environmental Consulting, LLC, the information contained in this *Second Quarter 2013 Groundwater Monitoring Report*, dated July 10, 2013 is true and correct, and that this declaration was executed at Los Angeles, California, on July 18, 2013.

Jack L. Bliss, Property Manager

J & P Realty

Table 1 Well Construction Details
Former Mondo Chrome Facility
South Gate, California

Well	Easting (ft) (a)	Northing (ft) (a)	TOC Flev (II MSL)	Total Depth (ft bgs)	Screen Slot Size (inches)	Screen Interval (ft bgs)	Installation Date	Well Diameter (inches)
Monitoring Well	s							
MW 1	6506548.06	1804974.39	109.60	55	0.02	30-55	Dec-98	2
MW 2	6506471.73	1804866.07	109.53	55	0.02	30-55	Dec-98	2
MW 3	6506536.10	1804847.21	109.66	55	0.02	30-55	Dec-98	2
MW 4	6506734.88	1804948.24	112.66	56	0.02	41-56	5/23/2013	4
MW 5	6506604.06	1804090.32	110.53	56	0.02	41-56	5/24/2013	4
MW 6	6506401.39	1804047.35	109.60	56	0.02	41-56	5/22/2013	4
Vapor Extraction	Wells							
VEW 1			n/a	50.5	0.04	15-45	6/27/1996	2
Vapor Monitorin	g Probes							
VP 1			n/a	40		19-20; 39-40	7/11/1996	1/4
VP 2			n/a	40		19-20; 39-40	7/11/1996	1/4
VP 3			n/a	40	SS tip	5, 20 & 40	2/19/2013	1/4
VP 4			n/a	40	SS tip	5, 20 & 40	2/20/2013	1/4
VP 5			n/a	40	SS tip	5, 20 & 40	2/20/2013	1/4
VP 6			n/a	40	SS tip	5, 20 & 40	2/20/2013	1/4

#### Notes:

TOC Elev = TOC elevation above MSL (NAVD88).

Abbreviations:

bgs = below ground surface ft = Feet

GS = Ground surface

n/a = Not applicable NA = Not accessible TOC = Top of casing

<sup>\* =</sup> Former groundwater and vapor extraction well
(a) = Survey coordinates in State Plane Coordinates; Zone 5.
MSL = Mean sea level

Table 2 Groundwater Elevations
1998 - 2013
Former Mondo Chrome Facility
South Gate, California

	Journ Gure, Ca	nij Ornia				
		TOC	Depth To	Groundwater		
Location	Gauging Date	Elevation	Water	Elevation	Elevation Change	Notes
25014	12 /7 /00	(ft MSL)	(fi BTOC)	(ft MSL)		
MW 1	12/7/98 3/3/99	109.40	41.58 40.71	67.82 68.69	0.87	
	6/24/99		40.36	69.04	0.35	
	9/17/99		40.31	69.09	0.05	
	12/20/99		40.35	69.05	-0.04	
	3/28/00		40.42	68.98	-0.07	
	6/26/00		40.50	68.90	-0.08	
	9/22/00		40.55	68.85	-0.05	
	12/18/00		41.78	67.62	-1.23	
	3/5/01		40.90 40.88	68.50 68.52	0.88 0.02	
	6/4/01 9/24/01		41.28	68.12	-0.40	
	12/13/01		41.71	67.69	-0.43	
	3/27/02		41.70	67.70	0.01	
	10/30/02		41.72	67.68	-0.02	
	5/6/03		43.18	66.22	-1.46	
	11/7/03		43.54	65.86	-0.36	
	3/14/08		43.58	65.82	-0.04	
	3/18/11		48.34	61.06	-4.76	
	6/20/11		48.49	60.91	-0.15	
	9/22/11 3/29/12		48.61 48.67	60.79 60.73	-0.12 -0.06	
	8/1/12		48.82	60.58	-0.00	
	3/15/13	109.60	49.07	60.53	-0.05	TOC surveyed by PLC 11/12
	6/21/13		49.33	60.27	-0.26	,,,
MW-2	12/7/98	109.45	41.68	67.77		
	3/3/99		40.81	68.64	0.87	
	6/24/99 9/17/99		40.45 $40.4$	69.00 69.05	0.36 0.05	
	12/20/99		40.43	69.02	-0.03	
	3/28/00		40.38	69.07	0.05	
	6/26/00		40.46	68.99	-0.08	
	9/22/00		40.47	68.98	-0.01	
	12/18/00		41.70	67.75	-1.23	
	3/5/01		40.83	68.62	0.87	
	6/4/01		40.71	68.74	0.12	
	9/24/01 12/13/01		41.11 41.49	68.34 67.96	-0.40 -0.38	
	3/27/02		41.40	68.05	0.09	
	10/30/02		41.43	68.02	-0.03	
	5/6/03		42.76	66.69	-1.33	
	11/7/03		43.26	66.19	-0.50	
	3/14/08		43.22	66.23	0.04	
	3/18/11		47.73	61.72	-4.51	
	6/20/11		47.88	61.57	-0.15	
	9/22/11		48.10	61.35	-0.22	
	3/29/12 8/1/12		48.30 48.49	61.15 60.96	-0.20 -0.19	
	3/15/13	109.53	48.71	60.82	-0.19	TOC surveyed by PLC 11/12
	6/21/13	107.50	48.98	60.55	-0.27	Toe surveyed by The 11/12
	0, 21, 10		10.70	00.00	0.27	
MW 3	12/7/98	109.61	41.78	67.83	***	
	3/3/99		40.94	68.67	0.84	
	6/24/99		40.59	69.02	0.35	
	9/17/99		40.56	69.05	0.03	
	12/20/99 3/28/00		40.61 40.54	69.00 69.07	-0.05 0.07	
	6/26/00		40.61	69.00	-0.07	
	9/22/00		40.60	69.01	0.01	
	,,					

Table 2 Groundwater Elevations
1998 - 2013
Former Mondo Chrome Facility
South Gate, California

Location	Gauging Date	TOC Elevation (ft MSL)	Depth To Water (ft BTOC)	Groundwater Elevation (ft MSL)	Elevation Change	Notes
MW 3 cont'd	12/18/00		41.85	67.76	-1.25	
	3/5/01		40.90	68.71	0.95	
	6/4/01		40.86	68.75	0.04	
	9/24/01		41.20	68.41	-0.34	
	12/13/01		41.48	68.13	-0.28	
	3/27/02		41.42	68.19	0.06	
	10/30/02		41.44	68.17	-0.02	
	5/6/03		42.86	66.75	-1.42	
	11/7/03		43.36	66.25	-0.50	
	3/14/08		43.43	66.18	-0.07	
	3/18/11		48.11	61.50	-4.68	
	6/20/11		48.25	61.36	-0.14	
	9/22/11		48.47	61.14	-0.22	
	3/29/12		48.65	60.96	-0.18	
	8/1/12		48.82	60.79	-0.17	
	3/15/13	109.66	49.06	60.60	-0.19	TOC surveyed by PLC 11/12
	6/21/13		49.34	60.32	-0.28	
MW 4	6/21/13	112.66	49.51	63.15	APPAR	TOC surveyed by PLC 6/13
MW 5	6/21/13	110.53	50.56	59.97		TOC surveyed by PLC 6/13
MW 6	6/21/13	109.60	49.24	60.36		TOC surveyed by PLC 6/13

Notes:

-- = No data; not quantifiable

Abbreviations:

TOC = Top of well casing

BTOC = Below top of well casing

ft = Feet

MSL = Mean sea level

n/a = Not applicable

NA = Not accessible

### Table 3 - Summary of VOC Analytical Detections in Groundwater 1998 to Present Former Mondo Chrome Facility South Gate, CA 90280

					L	SEPA 8260B (	μg/L)			
Well	Sample Date	PCE	TCE	cis- 1,2-DCE	trans- 1,2-DCE	1,1-DCE	VC	1,2-DCA	1,2,3-TCP	1,4-Dioxane
	12/7/98	110	140	6.8	NA	<1	<1	<0.5	NA	NA
	3/3/99	140	190	<10	NA	<16	<20	<10	NA	NA
	6/24/99	600	780	<25	NA	<40	<50	<25	NA	NA
	9/17/99	<i>7</i> 07	824	9.4	NA	1.9	1.9	< 0.5	NA	NA
	12/20/99	395	635	10	NA	1.6	<1	< 0.5	NA	NA
	3/28/00	368	538	11	NA	1.9	<1	< 0.5	NA	NA
	6/26/00	663	909	125	NA	< 0.8	<1	< 0.5	NA	NA
	9/22/00	111	150	< 0.5	NA	2.5	<1	< 0.5	NA	NA
	12/18/00	616	116	14	2.1	1.4	<1	< 0.5	NA	NA
	3/5/01	670	330	11	2.2	2.7	3.4	0.65	NA	NA
	6/4/01	420	800	12	< 0.8	1.6	<1	<1	NA	NA
	9/24/01	430	890	17	<10	<10	<10	<5	NA	NA
MW1	12/13/01	420	890	12	<1	1.9	<1	< 0.5	NA	NA
NIVV 1	3/27/02	590	980	18	< 5.0	<5	<5	<2.5	NA	NA
	10/30/02	500	880	12	<10	<10	<5	<5	NA	NA
	5/6/03	640	1,000	17	<10	<10	<5	<5	NA	NA
	11/7/03	510	820	15	<1	2.3	0.9	< 0.5	NA	NA
	3/14/08	310	560	13	<1	<1	< 0.5	< 0.5	< 5.0	5.8
	3/18/11	26	250	48	<1	<1	<1	<1	<1	NA
	6/20/11	38	660	86	4.6	<1	<1	<1	<1	NA
	9/22/11	3.9	130	58	1.6	<1	<1	<1	<1	NA
	3/29/12	11	150	16	5.7	<1	<1	<1	<1	NA
	8/1/12	7.6	240	72	6.2	<1	<1	<1	<1	NA
	3/15/13	19	200	120	< 0.5	< 0.5	< 0.5	< 0.5	<1	NA
	6/21/13	30	200	96	5.4	< 0.5	< 0.5	< 0.5	<1	<2
	12/7/98	11	77	16	NA	<1	<1	<0.5	NA	NA
	3/3/99	6.5	130	13	NA	<16	<5	<2.5	NA	NA
MW2	6/24/99	20	160	13	NA	<40	<10	<5	NA	NA
	9/17/99	15	156	21	NA	1.9	<1	< 0.5	NA	NA
	12/20/99	27	158	18	NA	1.6	<1	< 0.5	NA	NA
	3/28/00	8.4	138	27	NA	1.9	<1	< 0.5	NA	NA

### Table 3 - Summary of VOC Analytical Detections in Groundwater 1998 to Present Former Mondo Chrome Facility South Gate, CA 90280

					Ľ	SEPA 8260B (	μg/L)			
Well	Sample Date	PCE	TCE	cis- 1,2-DCE	trans- 1,2-DCE	1,1-DCE	VC	1,2-DCA	1,2,3-TCP	1,4-Dioxane
MW2 cont'd	6/26/00	17	101	230	NA	<0.8	<1	<0.5	NA	NA
	9/22/00	3.8	72.6	< 0.5	NA	2.5	<1	< 0.5	NA	NA
	12/18/00	12	92	28	2.1	1.4	<1	< 0.5	NA	NA
	3/5/01	7.1	50	19	2.2	2.7	1.2	< 0.5	NA	NA
	6/4/01	3	86	24	< 0.8	1.6	<1	< 0.5	NA	NA
	9/24/01	3.1	94	45	<10	<10	<1	< 0.5	NA	NA
	12/13/01	2.9	98	34	<1	1.9	<1	< 0.5	NA	NA
	3/27/02	4.1	120	46	1.1	<5	<1	< 0.5	NA	NA
	10/30/02	5	90	62	1.3	<10	< 0.5	< 0.5	NA	NA
	5/6/03	2.9	97	53	1.4	<10	< 0.5	< 0.5	NA	NA
	11/7/03	3.3	90	52	1.2	2.3	< 0.5	< 0.5	NA	NA
	3/14/08	2.2	68	43	<1	<1	< 0.5	< 0.5	<5	<2
	3/18/11	1.8	4.9	14	<1	<1	<1	<1	<1	NA
	6/20/11	<1	12	24	<1	<1	<1	<1	<1	NA
	9/22/11	<1	5.2	9.6	<1	<1	<1	<1	<1	NA
	3/29/12	<1	6.1	21	<1	<1	<1	<1	<1	NA
	8/1/12	<1	5.4	11	<1	<1	<1	<1	<1	NA
	3/15/13	<0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<1	NA
	6/21/13	7	9.6	16	< 0.5	<0.5	< 0.5	<0.5	<1	<2
000000000000000000000000000000000000000	12/7/98	9.3	<b>7</b> 5	10	NA	2	<1	<0.5	NA	NA
	3/3/99	5.1	100	6.4	NA	<4	<5	<2.5	NA	NA
	6/24/99	7.4	110	7.3	NA	<8	<10	<5	NA	NA
	9/17/99	6.1	145	12	NA	1.2	2.3	1.2	NA	NA
	12/20/99	4.4	43	3.6	NA	< 0.8	<1	< 0.5	NA	NA
	3/28/00	4.7	114	13	NA	1.7	<1	0.9	NA	NA
MW3	6/26/00	26	92	< 0.5	NA	< 0.8	<1	< 0.5	NA	NA
	9/22/00	7.1	66	4.97	NA	1.6	<1	< 0.5	NA	NA
	12/18/00	11	80	13	1.9	1.1	<1	< 0.5	NA	NA
	3/5/01	7	47	11	2	2.2	1.4	1.2	NA	NA
	6/4/01	2.4	56	9.2	< 0.8	0.85	<1	< 0.5	NA	NA
	9/24/01	2.5	72	17	<1	1.4	<1	1.0	NA	NA

### Table 3 - Summary of VOC Analytical Detections in Groundwater 1998 to Present Former Mondo Chrome Facility South Gate, CA 90280

					τ	JSEPA 8260B (	USEPA 8260B (µg/L)									
Well	Sample Date	PCE	TCE	cis- 1,2-DCE	trans- 1,2-DCE	1,1-DCE	VC	1,2-DCA	1,2,3-TCP	1,4-Dioxane						
MW 3 cont'd	12/13/01	3.1	67	11	<1	1.3	<1	<0.5	NA	NA						
	3/27/02	3.4	80	14	<1	1.7	<1	1.0	NA	NA						
	10/30/02	13	72	18	<1	1.2	< 0.5	< 0.5	NA	NA						
	5/6/03	3.5	63	12	<1	1.5	< 0.5	0.66	NA	NA						
	11/7/03	1.5	61	13	<1	1.5	0.59	< 0.5	NA	NA						
	3/14/08	1.2	49	25	<1	<1	< 0.5	< 0.5	< 5.0	<2						
-	3/18/11	9.8	27	13	<1	<1	<1	<1	<1	NA						
	6/20/11	4.5	19	21	<1	<1	<1	<1	<1	NA						
-	9/22/11	2.5	13	19	<1	<1	<1	<1	<1	NA						
	3/29/12	1.8	7.3	7.6	<1	<1	<1	<1	<1	NA						
	8/1/12	2.4	9.4	9.2	<1	<1	<1	<1	<1	NA						
	3/15/13	12	25	< 0.5	< 0.5	< 0.5	< 0.5	< 0.5	<1	NA						
	6/21/13	18	33	14	<0.5	<0.5	<0.5	<0.5	<1	<2						
MW 4	6/21/13	< 0.5	7	2.8	< 0.5	< 0.5	<0.5	<0.5	<1	<2						
MW 5	6/21/13	2.3	130	16	<0.5	<0.5	<0.5	<0.5	<1	<2						
MW 6	6/21/13	1.6	210	55	<0.5	<0.5	<0.5	<0.5	<1	<2						
	CA MCL	5	5	6	10	6	0.5	0.5	NE	NE						
Notes: All other analy	tes were not dete	ected.					Abbreviation PCE = Tetrac									
•	ed at or above th		oratory detec	tion limit.		TCE = Trichloroethene										
ug/L = Microg							DCE = Dichlo									
NA = Not anal	_						VC = Vinyl cl									
	yzeu ifornia Maximur	n Contaminant	t Level for dr	inking water			DCA = Dicho									
NE = None Est							TCP = Trichle									
140110 1130	SECTION OF						. C. IIICIII	opropunc								

### Table 4 - Summary of Metal Analytical Detections in Groundwater 1998 to Present Former Mondo Chrome Facility South Gate, CA 90280


Well	Sample	Total	Hexavalent	Cadmium	Nickel	Total
7761	Date	Chromium	Chromium			Cyanide
	12/7/98	NA	NA	NA	NA	NA
	3/3/99	19	<20	<4	NA	NA
	6/24/99	19	<20	<4	NA	NA
	9/17/99	16	<20	<4	NA	NA
	12/20/99	37	<20	<3	NA	NA
	3/28/00	4	NA	NA	NA	NA
	6/26/00	46	NA	NA	NA	NA
	9/22/00	<3	NA	NA	NA	NA
	12/18/00	20	<20	<3	NA	NA
	3/5/01	11	<20	<3	NA	NA
	6/4/01	19	NA	<3	NA	NA
	9/24/01	8.42	<1	<5	NA	NA
MW 1	12/13/01	22.5	<1	<5	NA	NA
1414.1	3/27/02	15.4	<1	<5	NA	NA
	10/30/02	<5	<1	<5	NA	NA
	5/6/03	<5	<1	<5	NA	NA
	11/7/03	8.03	<1	<5	NA	NA
	3/14/08	<5	< 0.2	<5	8.75	<50
	3/18/11	NA	NA	NA	NA	NA
	6/20/11	NA	NA	NA	NA	NA
	9/22/11	NA	NA	NA	NA	NA
	3/29/12	NA	NA	NA	NA	NA
	8/1/12	NA	NA	NA	NA	NA
	3/15/13	<10	<10	<10	<10	<50
	6/21/13	<10	<10	<10	<10	<b>&lt;</b> 50
***************************************	12/7/98	NA	NA	NA	NA	NA
	3/3/99	33	<20	<4	NA	NA
	6/24/99	50	<20	<4	NA	NA
	9/17/99	40	<20	<4	NA	NA
	12/20/99	18	<20	<3	NA	NA
	3/28/00	19	NA	NA	NA	NA
	6/26/00	38	NA	NA	NA	NA
	9/22/00	17	NA	NA	NA	NA
	12/18/00	20	<20	<3	NA	NA
MW 2	3/5/01	23	<20	3	NA	NA
	6/4/01	28	NA	<3	NA	NA
	9/24/01	6.73	<1	<5	NA	NA
	12/13/01	12.1	<1	<5	NA	NA
	3/27/02	9.7	<1	<5	NA	NA
	10/30/02	18	<1	<5	NA	NA
	5/6/03	<b>&lt;</b> 5	<1	<5	NA	NA
	11/7/03	<b>&lt;</b> 5	<1	<5	NA	NA
	3/14/08	6.41	<1	<5	10.3	<50

### Table 4 - Summary of Metal Analytical Detections in Groundwater 1998 to Present Former Mondo Chrome Facility South Gate, CA 90280


				Metals (µg/L)		
Well	Sample Date	Total Chromium	Hexavalent Chromium	Cadmium	Nickel	Total Cyanide
MW2 cont'd	3/18/11	NA	NA	NA	NA	NA
	6/20/11	NA	NA	NA	NA	NA
	9/22/11	NA	NA	NA	NA	NA
	3/29/12	NA	NA	NA	NA	NA
	8/1/12	NA	NA	NA	NA	NA
	3/15/13	<10	<10	<10	<10	<50
	6/21/13	<10	<10	<10	<10	<50
000000000000000000000000000000000000000	12/7/98	NA	NA	NA	NA	NA
	3/3/99	68	<20	<4	NA	NA
	6/24/99	50	<20	<4	NA	NA
	9/17/99	58	<20	<4	NA	NA
	12/20/99	37	<20	<3	NA	NA
	3/28/00	19	NA	NA	NA	NA
	6/26/00	44	NA	NA	NA	NA
	9/22/00	20	NA	NA	NA	NA
	12/18/00	30	<20	<3	NA	NA
	3/5/01	24	<20	6	NA	NA
	6/4/01	26	NA	3	NA	NA
	9/24/01	7.74	<1	<5	NA	NA
MW 3	12/13/01	9.4	<1	<5	NA	NA
	3/27/02	11.8	<1	<5	NA	NA
	10/30/02	12	<1	<5	NA	NA
	5/6/03	8	<1	<5	NA	NA
	11/7/03	5.04	<1	<5	NA	NA
	3/14/08	<5	< 0.2	<5	21	<50
	3/18/11	NA	NA	NA	NA	NA
	6/20/11	NA	NA	NA	NA	NA
	9/22/11	NA	NA	NA	NA	NA
	3/29/12	NA	NA	NA	NA	NA
	8/1/12	NA	NA	NA	NA	NA
	3/15/13	<10	<10	<10	<10	<50
	6/21/13	<10	<10	<10	<10	<50
MW 4	6/21/13	<10	<10	<10	<10	<50
MW 5	6/21/13	<10	<10	<10	<10	<50
MW 6	6/21/13	<10	<10	<10	<10	<50
	CAMCL	50	50°	5	100	150


### Table 4 - Summary of Metal Analytical Detections in Groundwater 1998 to Present Former Mondo Chrome Facility South Gate, CA 90280


				Metals (μg/L)		
Well	Sample Date	Total Chromium	Hexavalent Chromium	Cadmium	Nickel	Total Cyanide
Notes:						
< = Not detected at or above the indicated laboratory detection limit.						
$\mu$ g/L = Micrograms per liter						
NA = Not analyzed						
CA MCL = California Maximum Contaminant Level for drinking water.						
a. Regulated ı				~		




SUBJECT SITE: 4933 Firestone Blvd, South Gate, 90280, Page & Grid 705 E3









# ATTACHMENT I

Well Location and Elevation Survey Data

June 2013

Pacific Land Consultants, Inc P.O. Box 3762 RPV, CA 90274 310-544-8689

### Well Monitoring

4933 Firestone, South Gate, CA

Monitor Well Locations & Elevations Horiz = State Plane Coordinates, Zone 5 Vert = NAVD 88 datum - BM-Y8412

All Elevations are on north edge of casing

#	N	E	EL	DESC.
1	1,804,847.21	6,506,536.10	109.66	MW-3
2	1,804,866.07	6,506,471.73	109.53	MW-2
3	1,804,974.39	6,506,548.06	109.60	MW-1
10	1,804,948.24	6,506,734.88	109.19	MW-4
12	1,805,047.35	6,506,401.39	109.60	MW-6
14	1,805,090.32	6,506,604.06	110.53	MW-5
5	1,804,719.14	6,507,133.84	110.69	DY-9343
6	1,804,698.99	6,507,117.50	111.36	Y-10775

# ATTACHMENT II

Well Sample Data Logs

### WELL SAMPLE DATA LOG

PROJECT: 4933 Firestone, South Gate, CA	DATE: / <sub>2</sub> /2///3	SAMPLER: CFL
	<u> </u>	

### WELL DATA

WELL NUMBER: MW 1	SCREEN INTERVAL: 30'-55' bgs
WELL TOTAL DEPTH: 55'	•
DEPTH TO WATER: 49.33	Pump #003795 (set at 53' to sample)

### WELL PURGING DATA

PURGING METHOD: low flow (dedicated pump)	VOLUME OF WATER PURGED: 2.5しゃ			
TIME STARTED: フリケ	TIME COMPLETED: FOO			
EQUIPMENT USED: Horiba U52 (LEC0409); Solinst Interface 122-003656-1				

### WELL PURGING PARAMETERS

Purging Parameters

Time Start/Stop	Purge Rate (ml/min)	Temp °C	pН	ORP (mV)	Cond (ms/cm)	Turbidity	DO (mg/L)
746	250	23.93	7.36	:-171	1:50	23.5	0.0
48		24.33	7.33	-179	1.53	22.9	0.0
50		24.61	7.33	-185	1.54	22.8	0,0
52		24,83	734	-189	1.53	22.2	0.0
54		24.94	7.35	-(91	1,53	20.7	త, O
56		25.19	7.35	-191	1.53	126	0,0
						± ***	3
	.25 L/min		<u>+</u> 0.1 units	<u>±</u> 10 mV	<u>*</u> 3%	<u>+</u> 10 NTUs	±0.3 mg/L

Sample No.	Quantity	Volume	Туре	Prese	rvative	A	nalysis
Disellente	3	4010	104	Lyce .		Jee 1	101C
Duplicate	1	11-1	11	1 4	<u> </u>	<u> </u>	<u> </u>
Sample	100	1/26		Samplers	;	1	0

Sample Time:	750	Samplers Signature:	<u>CH</u>
Comments:			

### WELL SAMPLE DATA LOG

	j		l	
PROJECT: 4933 Firestone, South Gate, CA	DATE: $l_0$	211	13	SAMPLER: CFL

#### WELL DATA

WELL NUMBER: MW 2	SCREEN INTERVAL: 30'-55' bgs
WELL TOTAL DEPTH: 55' (53.8' soft bottom)	
DEPTH TO WATER: 48.98	Pump #003794 (set at 52' to sample)

### WELL PURGING DATA

PURGING METHOD: low flow (dedicated pump)	VOLUME OF WATER PURGED: 2 しキ			
TIME STARTED: 1002	TIME COMPLETED: 10/6			
EQUIPMENT USED: Horiba U52 (LEC0409); Solinst Interface				

### WELL PURGING PARAMETERS

**Purging Parameters** 

Time	Purge Rate	Temp		ORP	Cond	_	DO
Start/Stop	(ml/min)	°C	pH	(mV)	(ms/cm)	Turbidity	(mg/L)
1002	300	25.53	7.30	-144	1,58	11.7	<b>ව</b>
04		25.93	1.28	-/39	,1.59	24.6	0
06		16.54	7.28	-/36	1.59	19.6	0
06		76,97	7.28	-135	1.60	16.8	0
10		7.7.35	7.28	-137	1,59	14,1	O.
12		27.71	7.29	-140	1.58	14.2	0
						, ,	
							•
	.25 L/min		± 0.1 units	<u>+</u> 10 mV	<u>+</u> 3%	<u>+</u> 10 NTUs	<u>+</u> 0.3 mg/L

Sample No.	Quantity	Volume	Type	Preserv	vative Analysis
	3	Home	Voit	Qu/	See Cetc
Duplicate	/	16	Poly	14	
	1	1/20	Petr	f :	0
Sample Time:	1014	_		Samplers Signature:	_CH

Comments:

### WELL SAMPLE DATA LOG

	. 1		
PROJECT: 4933 Firestone, South Gate, CA	DATE: 6/21	1/13	SAMPLER: CFL

### WELL DATA

WELL NUMBER: MW 3	SCREEN INTERVAL: 30'-55' bgs
WELL TOTAL DEPTH: 55' (54.55' soft botto	m)
DEPTH TO WATER: 49.335 (49.3	Pump #003800 (set at 53' to sample)

#### WELL PURGING DATA

PURGING METHOD: low flow (dedicated pump)	VOLUME OF WATER PURGED: ∠ L +				
TIME STARTED: $1036$	TIME COMPLETED: 1050				
EQUIPMENT USED: Horiba U52 (LEC0409); Solinst Interface					

### WELL PURGING PARAMETERS

Purging Parameters

				1			
Time Start/Stop	Purge Rate (ml/mln)	Temp °C	pН	ORP (mV)	Cond (ms/cm)	Turbidity	DO (mg/L)
1036	300	26.20	7.25	-197	2.86	22.5	0
38		26.09	7, 24	-198	2.90	13.9	0
40		26.13	7.22	-188	2.88	9.2	0
42		26.30	7.20	-176	2.86	11.9	0
44		26.53	7.19	-/7/	2.87	14.5	0
46		26.13	7,19	-164	2.87	14,0	0
		,					
							, 40. 1, 1
						المحديد الم	
	.25 L/min		± 0.1 units	<u>±</u> 10 mV	± 3%	<u>±</u> 10 NTUs	±0.3 mg/L

Sample No.	Quantity	Volume	Туре	Prese	rvative	Analysis
	3	Youl	<i>U</i> 014	Lie		Salde
Duplicate	/	10	Poly	1.1		1
	1	1/26	Poly	14		0

Sample Time:	1048	Samplers Signature:	OF
Comments:	,		<i>O</i>

### WELL SAMPLE DATA LOG

			<u> </u>	
PROJECT: 4933 Firestone, South Gate, CA	DATE: (p)	211	in	SAMPLER: CFL
		1	,	

### WELL DATA

WELL NUMBER: MW 4	SCREEN INTERVAL: 41'-56' bgs
WELL TOTAL DEPTH: 56'	
DEPTH TO WATER: 49.51	Pump# 00 379 (set at 53')

#### WELL PURGING DATA

PURGING METHOD: low flow (dedicated pump)	VOLUME OF WATER PURGED: 3レド
TIME STARTED: 714	TIME COMPLETED: 7/8
EQUIPMENT USED: Horiba U52 (LEC0409); Solin	st Interface 127-003656-1

### WELL PURGING PARAMETERS

Purging Parameters

Time Start/Stop	Purge Rate (ml/min)	Temp °C	pН	ORP (mV)	Cond (ms/cm)	Turbidity	DO (mg/L)
704	300	23,04	10.93	-37	11/6	18.6	1,56
06		23.01	6.95	-55	1.17	13.1	0.75
06		23.20	4.96	-64	1.18	11.5	0,13
10		23.57	6.96	- 74	1.18	11.4	6.0
12		23,92	6.94	-77	1.18	10.6	0.0
14		24.19	6.95	-20	1.17	8.3	0,0
, and the same of							
						خودهر ≟	
	.25 L/min		<u>+</u> 0.1 units	<u>+</u> 10 mV	<u>±</u> 3%	<u>±</u> 10 NTUs	±0.3 mg/L

Sample No.	Quantity	Volume	Type	Preser	vative	An	alysis
	-3	40 ml	VOA	Jue			sa Colo
Duplicate	1	14	Poly	11			,
Sample Time:	716	thi	Poly	Samplers Signature:		<i>C</i> 2	K

#### WELL SAMPLE DATA LOG

			)	
PROJECT: 4933 Firestone, South Gate, CA	DATE: 6/	211	13	SAMPLER: CFL

### WELL DATA

WELL NUMBER: MW 5	SCREEN INTERVAL: 41'-56' bgs
WELL TOTAL DEPTH: 56.25'	
DEPTH TO WATER: 50.561	Pump # 003792 (set at 53')

### WELL PURGING DATA

PURGING METHOD: low flow (dedicated pump)	VOLUME OF WATER PURGED: 2.5ムナ
TIME STARTED: & 24	TIME COMPLETED: よっと
EQUIPMENT USED: Horiba U52 (LEC0409); Solins	st Interface 122 - 00 36 56 - 1

### WELL PURGING PARAMETERS

Purging Parameters

	T .		urging i are		1		
Time Start/Stop	Purge Rate (ml/min)	Temp °C	pН	ORP (mV)	Cond (ms/cm)	Turbidity	DO (mg/L)
824	750	22.92	7.22	-153	1.82	2.5	0
74		22.74	7.20	-168	1.84	1.2	0
<u>25</u>		22.56	7.17	7/72	1.85	0.1	0
30		22.91	7.17	-172	1.85	0.0	0
32		22.99	7.16	<i>(173</i> )	1.86	0.0	O
34		25,26	7.15	-171	1.86	6,3	0
'			·	,	,		
						ديك رخو عد -	
	.2-,5 L/min		<u>+</u> 0.1 units	<u>+</u> 10 mV	<u>+</u> 3%	<u>±</u> 10 NTUs	<u>+</u> 0.3 mg/L

Sample No.	Quantity	Volume	Type	Preservativ	ve Ar	alysis
	3	40 ml	V04	Qce	Sae	Colc
Duplicate	1	16	Poly	11		<u> </u>
	1	1/26	į i	1.		
Sample Time:	831	e O		Samplers Signature:	C	H

Comments:

### WELL SAMPLE DATA LOG

	· / · /	$f_{}$	
PROJECT: 4933 Firestone, South Gate, CA	DATE: し/レリ/	13	SAMPLER: CFL

#### WELL DATA

WELL NUMBER: MW 6	SCREEN INTERVAL: 41'-56' bgs
WELL TOTAL DEPTH: 56'	
DEPTH TO WATER: 49,24	Pump # 003793 (set at 53')

### WELL PURGING DATA

PURGING METHOD: low flow (dedicated pump)	VOLUME OF WATER PURGED: ろのしせ
TIME STARTED: Y/L	TIME COMPLETED: 926
EQUIPMENT USED: Horiba U52 (LEC0409); Solins	st Interface /22-003と56-/

### WELL PURGING PARAMETERS

Purging Parameters

Time Start/Stop	Purge Rate (ml/min)	Temp °C	рH	ORP (mV)	Cond (ms/cm)	Turbidity	DO (mg/L)
912	300	23.70	7.24	-182	1.85	9.6	0
14		23.75	7.21	-187	1.85	8.5	0
16		23.91	7.20	-190	1.86	8.6	0
18		24.38	7,19	-188	1.87	9.3	0
70		24.55	7.18	-187	1.81	8.8	0
22		24.95	7.18	-185	1.87	8.4	0
					r		
						يودهم ش	
	.25 L/min		± 0.1 units	± 10 mV	± 3%	± 10 NTUs	<u>+</u> 0.3 mg/L

Sample No.	Quantity	Volume	Туре	Preservative	Analysis
	3	40 M	YOA	Ine !	See CofC
Duplicate	1	14	Poly	te	i i
Sample Time:	924	1/26	ii'	ા Samplers Signature:	-CH

Comments:

# ATTACHMENT III

Laboratory Report of Analytical Results (Groundwater) and Chain-of-Custody Record

# AL ECH Environmental Laboratories



6814 Rosecrans Avenue, Paramount, CA 90723-3146 Telephone: (562) 272-2700

Fax: (562) 272-2789

### **ANALYTICAL RESULTS\***

Phone: (562) 799-9866

Fax: (562) 799-1963

Matrix: Water

CTEL Project No: CT217-1306140

Client Name:

Leymaster Environmental

5500 E. Atherton Street, Suite 210

Long Beach, CA 90815

Attention:

Mr. Charles Lindeman

Project ID:

Project Name:

4933 Firestone

Date Sampled: Date Received: 06/21/13 @ 07:58 am

06/21/13 @ 12:30 p.m.

Date Analyzed:

06/21/13

Date Reported:

07/02/13

Laboratory ID: Client Sample ID:	1306-140-1 MW1	1306-140-2 MW2	1306-140-3 MW3	Method	Units:	Detection Limit
Dilution	1	1	1			
Dichlorodifluoromethane	ND	ND	ND	EPA 8260B	ug/L	1
Chloromethane	ND	ND	ND	EPA 8260B	ug/L	î
Vinyl Chloride	ND	ND	ND	EPA 8260B	ug/L	0.5
Bromomethane	ND	ND	ND	EPA 8260B	ug/L	1
Chloroethane	ND	ND	ND	EPA 8260B	ug/L	1
Trichlorofluoromethane	ND	ND	ND	EPA 8260B	ug/L	1
Iodomethane	ND	ND	ND	EPA 8260B	ug/L	1
Acetone	ND	ND	ND	EPA 8260B	ug/L	10
1,1-Dichloroethene	ND	ND	ND	EPA 8260B	ug/L	0.5
t-Butyl Alcohol (TBA)	ND	ND	ND	EPA 8260B	ug/L	10
Methylene Chloride	ND	ND	ND	EPA 8260B	ug/L	10
Freon 113	ND	ND	ND	EPA 8260B	ug/L	5
Carbon disulfide	ND	ND	ND	EPA 8260B	ug/L	. 1
Trans, 1,2-Dichloroethene	5.4	ND	ND	EPA 8260B	ug/L	0.5
Methyl-tert-butyl-ether(MtBE)	ND	ND	ND	EPA 8260B	ug/L	1
1,1-Dichloroethane	ND	ND	ND	EPA 8260B	ug/L	0.1
Vinyl acetate	ND	ND	ND	EPA 8260B	ug/L	10
Diisopropyl Ether (DIPE)	ND	ND	ND	EPA 8260B	ug/L	1
Methyl Ethyl Ketone	ND	ND	ND	EPA 8260B	ug/L	10
Cis, 1,2-Dichloroethene	96	16	14	EPA 8260B	ug/L	0.5
Bromochloromethane	ND	ND	ND	EPA 8260B	ug/L	1
Chloroform	ND	ND	ND	EPA 8260B	ug/L	1
2,2-Dichloropropane	ND	ND	ND	EPA 8260B	ug/L	1
Ethyl-t-butyl ether (ETBE)	ND	ND	ND	EPA 8260B	ug/L	- 1
1,1,1-Trichloroethane	ND	ND	ND	EPA 8260B	ug/L	1
1,2-Dichloroethane	ND	ND	ND	EPA 8260B	ug/L	0.5
1,1-Dichloropropene	ND	ND	ND	EPA 8260B	ug/L	- 1
Carbon Tetrachloride	ND	ND	ND	EPA 8260B	ug/L	0.5
Benzene	ND	ND	ND	EPA 8260B	ug/L	0.5
t-Amyl Methyl Ether (TAM)	ND	ND	ND	EPA 8260B	ug/L	1
1,2-Dichloropropane	ND	ND	ND	EPA 8260B	ug/L	
Trichloroethene	200	9.6	33	EPA 8260B	ug/L	0.5
Dibromomethane	ND	ND	ND	EPA 8260B	ug/L	
Bromodichloromethane	ND	ND	ND	EPA 8260B	ug/L	<u>.</u>
2-Chloroethylvinylether	ND	ND	ND	EPA 8260B	ug/L	<b></b>
Cis, 1,3-Dichloropropene	ND	ND	ND	EPA 8260B	ug/L	1
4-Methyl-2-pentanone(MI)	ND	ND	ND	EPA 8260B	ug/L	10
Trans,1,3-Dichloropropene	ND	ND	ND	EPA 8260B	ug/L	1
Toluene	ND	ND	ND	EPA 8260B	ug/L.	0.5
1,1,2-Trichloroethane	ND	ND	ND	EPA 8260B	ug/L	1

CTEL Project No: CT217-1306140

Project ID:

Project Name: 4933 Firestone

Laboratory ID: Client Sample ID:	1306-140-1 MW1	1306-140-2 MW2	1306-140-3 MW3	Method	Units	Detection Limit
1,2-Dibromoethane(EDB)	ND	ND	ND	EPA 8260B	ug/L	0.5
1,3-Dichloropropane	ND	ND	ND	EPA 8260B	ug/L	1
Dibromochloromethane	ND	ND	ND	EPA 8260B	ug/L	1
2-Hexanone	ND	ND	ND	EPA 8260B	ug/L	10
Tetrachloroethene	30	7.0	18	EPA 8260B	ug/L	0.5
Chlorobenzene	ND ·	ND	ND	EPA 8260B	ug/L	1
1,1,1,2-Tetrachloroethane	ND	ND	ND	EPA 8260B	ug/L	1
Ethylbenzene	ND	ND	ND	EPA 8260B	ug/L	0.5
m.p-Xylene	ND	ND	ND	EPA 8260B	ug/L	0.5
Bromoform	ND	ND	ND	EPA 8260B	ug/L	1
Styrene	ND	ND	ND	EPA 8260B	ug/L	
o-Xylene	ND	ND	ND	EPA 8260B	ug/L	0.5
1,1,2,2-Tetrachloroethane	ND	ND	ND	EPA 8260B	ug/L	1
1,2,3-Trichloropropane	ND	ND	ND	EPA 8260B	ug/L	1
Isopropylbenzene	ND	ND	ND	EPA 8260B	ug/L	. 1
Bromobenzene	ND	ND	ND	EPA 8260B	ug/L	1
2-Chlorotoluene	ND	ND	ND	EPA 8260B	ug/L	1
n-Propylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
4-Chlorotoluene	ND	ND	ND	EPA 8260B	ug/L	1
1,3,5-Trimethylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
Tert-Butylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,2,4-Trimethylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
Sec-Butylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,3-Dichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,4-Dichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
p-Isopropyltoluene	ND	ND	ND	EPA 8260B	ug/L	1
1,2-Dichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
n-Butylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,2 Dibromo-3-Chloropropand	e ND	ND	ND	EPA 8260B	ug/L	. 1
1,2,4-Trichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
Naphthalene	ND	ND	ND	EPA 8260B	ug/L	1
1,2,3-Trichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
Hexachlorobutadiene	ND	ND	ND	EPA 8260B	ug/L	. 1
Ethanol	ND	ND	ND	EPA 8260B	ug/L	50
1,4-Dioxane*	ND	ND	ND	EPA 8260B	ug/L	2

ND = Not Detected at the indicated Detection Limit

SURROGATE SPIKE	i de la martina de la compansión de la comp	% SUF	ROGATE RECOVERY	Co	ontrol Limit
Dibromofluoromethane	96	94	94		70-130
1,2 Dichloromethaned4	95	95	93		70-130
Toluene-d8	95	94	95		70-130
Bromofluorobenzene	94	93	93		70-130

Client Name: Leymaster Environmental

5500 E. Atherton Street, Suite 210

Long Beach, CA 90815

Attention: Mr.

Mr. Charles Lindeman

Project ID:

Project Name:

4933 Firestone

Date Sampled:

06/21/13 @ 07:16 am

Date Received:

06/21/13 @ 12:30 p.m.

Date Analyzed:

06/21/13

Date Reported:

07/02/13

Laboratory ID: Client Sample ID:	at Sample ID: MW4 MW5 MW6		Method	Units:	Detection Limit	
Dilution	1	1	1			
Dichlorodifluoromethane	ND	ND	ND	EPA 8260B	ug/L	1
Chloromethane	ND	ND ND	ND	EPA 8260B	ug/L ug/L	1
Vinyl Chloride	ND	ND	ND	EPA 8260B	ug/L ug/L	0.5
Bromomethane	ND	ND	ND	EPA 8260B	ug/L ug/L	1
Chloroethane	ND ND	ND ND	ND ND	EPA 8260B	ug/L	1
Trichlorofluoromethane	ND	ND	ND	EPA 8260B	ug/L	1
Iodomethane	ND ND	ND ND	ND	EPA 8260B	ug/L ug/L	e en <b>i</b> nstant
Acetone	ND	ND	ND	EPA 8260B	ug/L ug/L	10
1,1-Dichloroethene	ND	ND ND	ND ND	EPA 8260B	ug/L	0.5
t-Butyl Alcohol (TBA)	ND	ND	ND	EPA 8260B	ug/L ug/L	10
Methylene Chloride	ND	ND ND	ND	EPA 8260B	ug/L	10
Freon 113	ND	ND	ND	EPA 8260B	ug/L	5
Carbon disulfide	ND	ND	ND ND	EPA 8260B	ug/L ug/L	1
Trans, 1,2-Dichloroethene	ND	ND	ND	EPA 8260B	ug/L ug/L	0.5
Methyl-tert-butyl-ether(MtBE)	ND	ND	ND	EPA 8260B	ug/L ug/L	1
1,1-Dichloroethane	ND	ND	ND	EPA 8260B	ug/L ug/L	0.1
Vinyl acetate	ND ND	ND	ND	EPA 8260B	ug/L ug/L	10
Diisopropyl Ether (DIPE)	ND	ND	ND	EPA 8260B	ug/L ug/L	10
Methyl Ethyl Ketone	ND ND	ND ND	ND ND	EPA 8260B	ug/L ug/L	10
Cis,1,2-Dichloroethene	2.8	16	55	EPA 8260B	ug/L ug/L	0.5
Bromochloromethane	ND	ND	ND	EPA 8260B	ug/L	
Chloroform	ND	ND	ND	EPA 8260B	ug/L	ning sa manunga <del>k</del> aban sa bilang M
The second secon	ND ND	ND ND	ND ND	EPA 8260B	ug/L	
2,2-Dichloropropane Ethyl-t-butyl ether (ETBE)	ND ND	ND	ND	EPA 8260B	ug/L ug/L	1
1,1,1-Trichloroethane	ND ND	ND ND	ND ND	EPA 8260B	ug/L .ug/L	autorio e in in <mark>l</mark> egal in 1991.
1,2-Dichloroethane	ND	ND	ND	EPA 8260B	ug/L	0.5
	ND ND	ND ND	ND ND	EPA 8260B	ug/L	1
1,1-Dichloropropene Carbon Tetrachloride	ND	ND	ND	EPA 8260B	ug/L ug/L	0.5
Benzene	ND ND	ND ND	ND ND	EPA 8260B	ug/L ug/L	0.5
t-Amyl Methyl Ether (TAM)	ND	ND	ND	EPA 8260B	ug/L ug/L	0.5
	ND	ND	ND ND	EPA 8260B	ug/L ug/L	1
1,2-Dichloropropane Trichloroethene	7.0	130	210	EPA 8260B	ug/L ug/L	0.5
Dibromomethane	7.0 ND	ND	ND	EPA 8260B	ug/L	1
Bromodichloromethane	ND	ND	ND	EPA 8260B	ug/L ug/L	1
2-Chloroethylvinylether	ND ND	ND	ND ND	EPA 8260B	ug/L	
Cis, 1,3-Dichloropropene	ND	ND	ND	EPA 8260B	ug/L	1
4-Methyl-2-pentanone(MI)	ND ND	ND ND	ND ND	EPA 8260B	ug/L ug/L	10
Trans,1,3-Dichloropropene	ND	ND	ND	EPA 8260B	ug/L	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Trans, 1,3-Dichioropropene Toluene	ND ND	ND ND	ND ND	EPA 8260B	ug/L ug/L	0.5
1,1,2-Trichloroethane	ND	ND ND	ND	EPA 8260B	ug/L	1
1,1,2~111cmorocmane	1417	MD	TAFA	DI A 0200D	α≅∖r	ı

Phone: (562) 799-9866

Fax: (562) 799-1963

Matrix: Water

Project ID:

Project Name: 4933 Firestone

Laboratory ID: Client Sample ID:	1306-140-4 MW4	1306-140-5 MW5	1306-140-6 MW6	Method	Units	Detection Limit
1,2-Dibromoethane(EDB)	ND	ND	ND	EPA 8260B	ug/L	0.5
1,3-Dichloropropane	ND	ND	ND	EPA 8260B	ug/L	1
Dibromochloromethane	ND	ND	ND	EPA 8260B	ug/L	1.15
2-Hexanone	ND	ND	ND	EPA 8260B	ug/L	10
Tetrachloroethene	ND	2.3	1.6	EPA 8260B	ug/L	0.5
Chlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,1,1,2-Tetrachloroethane	ND	ND	ND	EPA 8260B	ug/L	1
Ethylbenzene	ND .	ND	ND	EPA 8260B	ug/L	0.5
m.p-Xylene	ND	ND	ND	EPA 8260B	ug/L	0.5
Bromoform	ND	ND	ND	EPA 8260B	ug/L	1
Styrene	ND	ND	ND	EPA 8260B	ug/L	1
o-Xylene	ND	ND	ND	EPA 8260B	ug/L	0.5
1,1,2,2-Tetrachloroethane	ND	ND	ND	EPA 8260B	ug/L	1
1,2,3-Trichloropropane	ND	ND	ND	EPA 8260B	ug/L	1
Isopropylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
Bromobenzene	ND	ND	ND	EPA 8260B	ug/L	1
2-Chlorotoluene	ND	ND	ND	EPA 8260B	ug/L	<b>1</b>
n-Propylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
4-Chlorotoluene	ND	ND	ND	EPA 8260B	ug/L	1
1,3,5-Trimethylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
Tert-Butylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,2,4-Trimethylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
Sec-Butylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,3-Dichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,4-Dichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
p-Isopropyltoluene	ND	ND	ND	EPA 8260B	ug/L	1
1,2-Dichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	
n-Butylbenzene	ND	ND	ND	EPA 8260B	ug/L	1
1,2 Dibromo-3-Chloropropane	ND	ND	ND	EPA 8260B	ug/L	ran dingaan d
1,2,4-Trichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
Naphthalene	ND	ND	ND	EPA 8260B	ug/L	1
1,2,3-Trichlorobenzene	ND	ND	ND	EPA 8260B	ug/L	1
Hexachlorobutadiene	ND	ND	ND	EPA 8260B	ug/L	
Ethanol	ND	ND	ND	EPA 8260B	ug/L	50
1,4-Dioxane*	ND	ND	ND	EPA 8260B	ug/L	2

ND = Not Detected at the indicated Detection Limit

SURROGATE SPIKE		% SUR	ROGATE RECOVE	RY	Control Limit
Dibromofluoromethane	94	95	92		70-130
1,2 Dichloromethaned4	94	93	93		70-130
Toluene-d8	92	95	92		70-130
Bromofluorobenzene	94	93	92		70-130

Client Name:

Leymaster Environmental

5500 E. Atherton Street, Suite 210

Long Beach, CA 90815

Attention:

Mr. Charles Lindeman

Project ID:

Project Name:

4933 Firestone

Date Sampled: Date Received: 06/21/13 @ 07:58 am

06/21/13 @ 12:30 p.m.

Date Analyzed:

06/21/13 - 06/26/13

Date Reported:

07/02/13

Date Reported:	07/02/13					
Laboratory ID:	1306-140-1	1306-140-2	1306-140-3	Method	Units	Detection
Client Sample ID:	MW1	MW2	MW3			Limit
Cadmium (Cd)	ND	ND	ND	SW846 6010B	mg/L	0.01
Chromium (Cr)	ND	ND	ND	SW846 6010B	mg/L	0.01
Nickel (Ni)	ND	ND	ND	SW846 6010B	mg/L	0.01
					en de la composition della com	
Acid, Extraction	06/21/13	06/21/13	06/21/13	SW846 3010	Date	
Chromium VI	A NO.	ND	ND	EPA 7196A	mg/L	0.01
Cyanide	ND	ND	ND	SM4500-CN-E	mg/L	0.05

Phone: (562) 799-9866

Fax: (562) 799-1963

Matrix: Water

Client Name:

Leymaster Environmental

5500 E. Atherton Street, Suite 210

Long Beach, CA 90815

Attention:

Mr. Charles Lindeman

Project ID:

Project Name:

4933 Firestone

Date Sampled:

06/21/13 @ 07:16 am

Date Received:

06/21/13 @ 12:30 p.m.

Date Analyzed:

06/21/13 - 06/26/13

Date Reported:

Cadmium (Cd)

Chromium (Cr)

Nickel (Ni)

Client Sample ID:

07/02/13

Laboratory ID:

1306-140-5 1306-140-4 MW4 MW5

1306-140-6 MW6

ND

SW846 6010B SW846 6010B SW846 6010B

Method

0.01 mg/L mg/L 0.01 0.01 mg/L

Acid, Extraction

06/21/13

06/21/13

ND

ND

ND

06/21/13

ND

ND

SW846 3010

Date

Phone: (562) 799-9866

Fax: (562) 799-1963

Units

Matrix: Water

0.01

Detection

Limit

Chromium VI Cyanide

ND ND

ND

ND

ND

ND ND ND ND

EPA 7196A SM4500-CN-E mg/L mg/L

0.05

ND = Not Detected at the indicated Detection Limit

Greg Tejárian

Laboratory Director

<sup>\*</sup>The results are base upon the sample received.

# AL LECH Environmental Laboratories



6814 Rosecrans Avenue, Paramount, CA 90723-3146 Telephone: (562) 272-2700

Fax: (562) 272-2789

### QA/QC Report

Method:

8015M

Matrix:

Water

Date Analyzed:

6/21/2013

Date Extracted:

6/21/2013

Perimeters	Conc.	ug/L	Spike	Spike Recovery		Control	Limits	RPD
	MS	MSD	Added	MS	MSD	Rec.	RPD	
TPH - Gasoline	948	933	1000	95	93	70-130	20	2
TPH - Diesel	1030	1051	1000	103	105	70-130	20	2

Perimeters	Method Blank	Units	Det. Limit	
TPH - Gasoline	ND	ug/L	50	
TPH - Diesel	ND	ug/L	50	

MS: Matrix Spike

MSD: Matrix Spike Duplicate

RPD: Relative Percent Difference of MS and MSD

## LAL LECH Environmental Laboratories



6814 Rosecrans Avenue, Paramount, CA 90723-3146 Telephone: (562) 272-2700.

Fax: (562) 272-2789

### QA/QC Report

Method:

8260B

Matrix:

Water

Date Analyzed:

6/21/2013

Date Extracted:

6/21/2013

Perimeters	Conc.	ug/L	Spike	Recovery	%	Control	Limits	RPD
·	MS	MSD	Added	MS	MSD	Rec.	RPD	
1,1-Dichloroethane	44	43	50	88	86	70-130	20	2
Benzene	48	48	50	96	96	70-130	20	0
Trichloroethene	49	49	50	98	98	70-130	20	0
Toluene	54	55	50	108	110	70-130	20	2
Chlorobenzene	43	41	50	86	82	70-130	20	4
m,p-Xylenes	102	107	100	102	107	70-130	20	5

MS: Matrix Spike

MSD: Matrix Spike Duplicate

RPD: Relative Percent Difference of MS and MSD

Perimeters	Method	Units	Det.
	Blank		Limit
1,1-Dichloroethene	ND	ug/L	1
Benzene	ND	ug/L	0.5
Trichloroethene	ND	uġ/L	0.5
Toluene	ND	ug/L	0.5
Chlorobenzene	ND	ug/L	0.5
m,p-Xylenes	ND	ug/L	0.6
MTBE	ND	ug/L	1
TBA	ND	ug/L	10
DIPE	ND	ug/L	1
ETBE	ND	ug/L	1
TAME	ND	ug/L	1
1,2-Dichloroethane	ND	ug/L	0.5
EDB	ND	ug/L	0.5
Ethylbenzene	ND:	ug/L	0.5
o-Xylene	ND	ug/L	0.6
TCE	ND	ug/L	1
PCE	ND	ug/L	1

Cal Teci	I Environmental I	<u> Laboratories</u>				L	ab Job	No	06		14:	$\supset$	Pageof
6814 Rose	crans Avenue, Paramount, : (562) 272-2700 Fax	CA 90723-3146						<u> </u>	_				
<u> </u>			,					Ch	aiı	10	of C	ust	tody Record
Client:	EYMKTER FO Charles Linds	o Cons (LEC	PI	hone:	<u> </u>	7866	ر چ		i	Turn	Aroui	ıd Tin	ne
Contact:	Charles Lind.	man	<del></del>	Fax: Rush									
Address:	5500 E. Alle	ton 4 #210	•	Normal					<u> </u>				
《	Long Beach, (	A- 90815											
Project:	4933 Fu	sytone 1	<u> </u>					_	$\frac{\mathbf{A}\mathbf{I}}{\mathbf{A}\mathbf{I}}$	naiys	es Reg	uesteo/	1 / / /
Sampled By:	4933 Fu O Lyndenan K Jame/Signature	ho phil					/:						
Lab ID Numbe	er Field ID	Date/Time Sampled		No.	Preserv.	Matrix						Ş	Comments
	NWI	6/21/13 758	40x2 VOTA 1241/26 POG	5	be	14,0	V.	/ /		V	✓ <u> </u>	/	RUZLBS LOW
	11.152	1014		5		1	V .	///	V	V	Sand .	4	Mils
	MU3	1048	100	5			/ ,		V	<b>V</b>			
	NW4	716		5		Para sa	1	/ /	1	1			
	465	V 936	, V	5	$\overline{V}$	V	<i>y</i> ,	VV		/	<i>-</i>	/	·
	NUL	6/21/13 924	Yest VOA IL 4 Yrt Pely	5	Jul	1/20		/	1	/		4	
		(				·			_				
									-	ļ			
		,											
Relinquished:	Chy 9+		Da	te / Ti	me: <u>6/2</u>	<u> 1/18                                  </u>				F	Receive	ed:	
Dispatched:			Da	ite / Ti	me:					(	Carrie	·;	
May :	orize the performance of th	e above indicated tests.	Da	ite / Ti		21/13	<b>G</b> 2	1530 J	 .h.?		Receiv	ed by	
CTELCCR.DOC ``				Cust	ody seal(s) i	n tact upoi	i iccei	proy 18	W!		YES		NO NONE

### ATTACHMENT IV

Non-Hazardous Waste Manifest No. 010418

Laboratory Report of Analytical Results (IDW) and Chain-of-Custody Record

A	NON-HAZARDOUS	1. Generator ID Number	2. Page	1 of 3. Emer	gency Response	Phone	4. Waste Tra	acking Nu	mber and and an
IĨ	WASTE MANIFEST	Not Required	1		) 786-620		· V		010418
	5. Generator's Name and Mailin	ng Address					than mailing addre	ss)	
	J&P Realty						ne Fadility:		
	1024 Cremshaw	Bouleverd Torrance CA 90501	1	493	3 Pireston	ie Blyd.	Southgate,	CAB	0280
	Generator's Phone: 6. Transporter 1 Company Nam	(310) 320-4621	,				U.S. EPA ID N	lumbar	
	6. Transponer i Company Nam KW Industria	ie .					0.5. EFA 10 1		*00
.	7. Transporter 2 Company Nam	10					U.S. EPA ID N		37 Styles
	7. Handportor 2 dompany ream						1		
	8. Designated Facility Name an	d Site Address					U.S. EPA ID N		
	Crosby & Overt						CADO	264021	019
	1830 W. 18th S	k. Long Beach: CA 90913							
"	Facility's Phone:	582-432-5448		•	-				-
	9. Waste Shipping Name	e and Description			10. Conta	iners	11. Total	12. Unit	
	.,, ,				No.	Type	Quantity	Wt./Vol.	
8	Non-Hazard	ous Waste Solids (Soli)			018	CM	12,690	p	
A							10/000	7	
GENERATOR	2.				- Ministra	260 a 3		. 67.	
Ö	Nor-Mazardi	ous Waste Liquids (Liquid)		.:	002	DH	80		
							14E		
	3.								
	4.						1 1 1		
						N			
	13. Special Handling Instruction	ns and Additional Information							
					Profile #				and the second
	KM Industrial J				Profile 4x				
	Weights & or V	diumes are approximate		Direc	i Sili io Ki	ā indusi	rial- (562)	796-6	
		1							
	14. GENERATOR'S CERTIFICATION OF THE CONTROL OF THE	ATION: I certify the materials described above on this	manifest are not s	Subject to federa Signature	il regulations for	reporting pro	per disposal of Ha	zardous V	vaste. Month Day Year
₩	38			Oignature	i de la comp	de sample	e de la companya de l	er.	[26] 28 13
	15. International Shipments	<u>Mirwa Mayar k</u> Tumu	П.		-				
INT'L	Transporter Signature (for expo	Import to U.S.	LLI Export	from U.S.	Port of en Date leav				
}	16. Transporter Acknowledgmer								
Ĕ	Transporter 1 Printed/Typed Na	Section .		Signature	1	e de	1	- Marie Marie	Month Day Year
SPC	2446010	<u>Seymull</u>			J. Janes Danisco	et puil.	Left Comme		<u>                                      </u>
TRANSPORTER	Transporter 2 Printed/Typed Na	ime *		"Signature I			1.		Month Day Year
-	17. Discrepancy			<u> </u>					
A	17a. Discrepancy Indication Spa	ace $\Box$			1	***************************************			<u> </u>
		L Quantity	Type	. L	J Residue		Partial Reje	ection	Full Rejection
				Mani	fest Reference N	lumber:			
≧	17b. Alternate Facility (or Gener	rator)					U.S. EPA ID N	lumber	
픙							1		
D F	Facility's Phone: 17c. Signature of Alternate Faci	like (as Congressed			······································		<u></u>		Month Day Year
DESIGNATED FACILITY	176. Dignature of Alternate Paci	may for deficiation)				,		. •	Month Day real
Š				1					
DES									
		or Operator: Certification of receipt of materials covere	d by the manifest	·····	in Item 17a				
U	Printed/Typed Name			Signature		٠			Month Day Year
V	1			1.					

## **ECH** Environmental Laboratories



6814 Rosecrans Avenue, Paramount, CA 90723-3146 Telephone: (562) 272-2700

Fax: (562) 272-2789

ANALYTICAL RESULTS\*

Phone: (562) 799-9866

Fax: (562) 799-1963

Matrix: Water

CTEL Project No: CT217-1306139

Client Name:

Leymaster Environmental

5500 E. Atherton Street, Suite 210

Long Beach, CA 90815

Attention:

Mr. Charles Lindeman

Project ID:

Project Name:

4933 Firestone

Date Sampled:

06/21/13 @ 11:15 am

Date Received:

06/21/13 @ 12:30 p.m.

Date Analyzed:

1,1,2-Trichloroethane

ND

06/21/13

Date Reported:

06/24/13

Laboratory ID; Client Sample ID:	1306-139-1 WD2		Method	Units:	Detection Limit
Dilution	1				
Dichlorodifluoromethane	ND		EPA 8260B	ug/L	1
Chloromethane	ND		EPA 8260B	ug/L	1
Vinyl Chloride	ND		EPA 8260B	ug/L	0.5
Bromomethane	ND		EPA 8260B	ug/L	1
Chloroethane	ND		EPA 8260B	ug/L	$\mathbf{i}$
Trichlorofluoromethane	ND		EPA 8260B	ug/L	1
Iodomethane	ND		EPA 8260B	ug/L	taka kalimatan
Acetone	ND		EPA 8260B	ug/L	10
1,1-Dichloroethene	ND		EPA 8260B	ug/L	0.5
t-Butyl Alcohol (TBA)	ND		EPA 8260B	ug/L	10
Methylene Chloride	ND	역에는 보는 바다 다리가 되는 때는 경험하다.	EPA 8260B	ug/L	10
Freon 113	ND		EPA 8260B	ug/L	5
Carbon disulfide	ND		EPA 8260B	ug/L	1
Trans, 1,2-Dichloroethene	ND		EPA 8260B	ug/L	0.5
Methyl-tert-butyl-ether(MtBE)	ND		EPA 8260B	ug/L	. 1
1,1-Dichloroethane	ND		EPA 8260B	ug/L	0.1
Vinyl acetate	ND		EPA 8260B	ug/L	10
Diisopropyl Ether (DIPE)	ND		EPA 8260B	ug/L	1
Methyl Ethyl Ketone	ND		EPA 8260B	ug/L	10
Cis,1,2-Dichloroethene	3.8		EPA 8260B	ug/L	0.5
Bromochloromethane	ND		EPA 8260B	ug/L	1
Chloroform	ND		EPA 8260B	ug/L	1
2,2-Dichloropropane	ND		EPA 8260B	ug/L	
Ethyl-t-butyl ether (ETBE)	ND		EPA 8260B	ug/L	1
1,1,1-Trichloroethane	ND ND		EPA 8260B	ug/L	1
1,2-Dichloroethane	ND		EPA 8260B	ug/L	0.5
1,1-Dichloropropene	ND		EPA 8260B	ug/L	1
Carbon Tetrachloride	ND		EPA 8260B	ug/L	0.5
Benzene	ND		EPA 8260B	ug/L	0.5
t-Amyl Methyl Ether (TAM)	ND		EPA 8260B	ug/L	1
1,2-Dichloropropane	ND		EPA 8260B	ug/L	
Trichloroethene	26		EPA 8260B	ug/L	0.5
Dibromomethane	ND		EPA 8260B	ug/L	1
Bromodichloromethane	ND		EPA 8260B	ug/L	1
2-Chloroethylvinylether	ND		EPA 8260B	ug/L	5
Cis, 1,3-Dichloropropene	ND	marten sasa arras sua summer ar esta esta en en en en en en	EPA 8260B	ug/L	1
4-Methyl-2-pentanone(MI)	ND		EPA 8260B	ug/L	10
Trans, 1,3-Dichloropropene	ND		EPA 8260B	ug/L	1
Toluene	ND		EPA 8260B	ug/L	0.5
1 ( 0 m : 1.1	TA TOP'N		ED 4 DO COD	/1	1

EPA 8260B

ug/L

Project ID:

Project Name: 4933 Firestone

Laboratory ID: Client Sample ID:	1306-139-1 WD2	Method U	nits Detection Limit
1,2-Dibromoethane(EDB)	ND	EPA 8260B u	g/L 0,5
1,3-Dichloropropane	ND	EPA 8260B u	g/L I
Dibromochloromethane	ND		g/L 1
2-Hexanone	ND	EPA 8260B u	g/L 10
Tetrachloroethene	7.9	EPA 8260B u	g/L 0.5
Chlorobenzene	ND	EPA 8260B u	g/L I
1,1,1,2-Tetrachloroethane	ND	EPA 8260B u	g/L 1
Ethylbenzene	ND .	EPA 8260B u	g/L 0.5
m.p-Xylene	ND	EPA 8260B u	g/L 0,5
Bromoform	ND	EPA 8260B u	g/L 1
Styrene	ND	EPA 8260B u	g/L 1
o-Xylene	ND	EPA 8260B u	g/L 0.5
1,1,2,2-Tetrachloroethane	ND	EPA 8260B u	g/L 1
1,2,3-Trichloropropane	ND	EPA 8260B u	g/L 1
Isopropylbenzene	ND		g/L 1
Bromobenzene	ND	EPA 8260B u	g/L 1
2-Chlorotoluene	ND	EPA 8260B u	g/L 1
n-Propylbenzene	ND	EPA 8260B u	g/L 1
4-Chlorotoluene	ND	EPA 8260B u	g/L 1
1,3,5-Trimethylbenzene	ND	EPA 8260B u	g/L 1
Tert-Butylbenzene	ND	EPA 8260B u	g/L 1
1,2,4-Trimethylbenzene	ND	EPA 8260B u	g/L 1
Sec-Butylbenzene	ND	EPA 8260B u	y∕L 1
1,3-Dichlorobenzene	ND	EPA 8260B u	g/L 1
1,4-Dichlorobenzene	ND	EPA 8260B u	yL 1
p-Isopropyltoluene	ND	EPA 8260B u	g/L 1
1,2-Dichlorobenzene	ND	EPA 8260B u	g/L 1
n-Butylbenzene	ND	EPA 8260B u	g/L 1
1,2 Dibromo-3-Chloropropane	ND	EPA 8260B u	g/L 1
1,2,4-Trichlorobenzene	ND	EPA 8260B u	g/L 1
Naphthalene	ND		g/L 1
1,2,3-Trichlorobenzene	ND	EPA 8260B u	g/L 1
Hexachlorobutadiene	ND	EPA 8260B u	g/L 1
Ethanol	ND		g/L 50

#### ND = Not Detected at the indicated Detection Limit

SURROGATE SPIKE	% SURROGATE RECOVERY	Co	ntrol Limit
Dibromofluoromethane 1,2 Dichloromethaned4			70-130 70-130
Toluene-d8	85		70-130
Bromofluorobenzene			70-130
R. Yoghon J. Fr			
Greg Tejiridh			
Laboratory Director			

<sup>\*</sup>The results are base upon the sample received.

# CAL TECH Environmental Laboratories

6814 Rosecrans Avenue, Faramount, CA 90723-3146 Telephone: (562) 272-2700

Fax: (562) 272-2789

### QA/QC Report

Method:

8260B

Matrix:

Water

Date Analyzed:

6/21/2013

Date Extracted:

6/21/2013

Perimeters	Conc.	ug/L	Spike	Recovery	%	Control	Limits	RPD
	MS	MSD	Added	MS	MSD	Rec.	RPD	
1.1-Dichloroethene	45	48	50	90	96	70-130	20	6
Benzene	47	50	50	94	100	70-130	20	6
Trichloroethene	47	49	50	94	98	70-130	20	4
Toluene	49	47	50	98	94	70-130	20	4
Chlorobenzene	48	46	50	96	92	70-130	20	4
m,p-Xylenes	94	96	100	94	96	70-130	20	2

MS: Matrix Spike

MSD: Matrix Spike Duplicate

RPD: Relative Percent Difference of MS and MSD

Perimeters	Method	Units	Det.		
	Blank		Limit		
1,1-Dichloroethene	ND	ug/L	1		
Benzene	ND	ug/L	0.5		
Trichloroethene	ND	ug/L	0.5		
Toluene	ND	ug/L	0.5		
Chlorobenzene	ND	ug/L	0.5		
m,p-Xylenes	ND	ug/L	0.6		
MTBE	ND	ug/L	1		
TBA	ND	ug/L	10		
DIPE	ND	ug/L	1		
ETBE	ND	ug/L	1		
TAME	ND	ug/L	1		
1,2-Dichloroethane	ND	ug/L	0.5		
EDB	ND	ug/L	0.5		
Ethylbenzene	ND	ug/L	0.5		
o-Xylene	ND	ug/L	0.6		
TCE	ND	ug/L	1		
PCE	ND	ug/L	1		

6814 F	losecrans	nvironmental L  Avenue, Paramount, (2) 272-2700 Fax:	CA 90723-3146				L	ab Jo	b No.	_0	<u>G</u>		3;	9	Page	of	<b>)</b>
· reich	ione: (50	a para a root a root.	(302) 272 2702						C	hai	n o	of (	Cu	isto	odv F	lecord	
Client: LEYMASTER END CONS (LEC)  Contact: Charles Lindeman  Address: 5500 E. Athertor St #210									~ ~ ~								•
Project: 4933 Firestone Sampled By: C. Lindeman Analyses Requested Name/Signature  Analyses Requested																	
Lab ID Nu	mber	Field ID	Date/Time Sampled	,	No.	Preserv.	Matrix		7						Co	mments	
		WD2	6/21/13 1115	to GSA	2	Dec	120	<b>V</b>									
			,														
***																	
												1			**************************************		
					<del> </del>			<b> </b>									
											<u> </u>						
					-							<del> </del>	+-				
Relinquisl	ned:	Ku) Z		Da	te / Ti	me: <u>6/2</u>	1/13		JL	I	LF	Recei	ived:				
Dispatched:				Date / Time: Carrier:							ier:				***************************************		
- Zi	ulhorize	the performance of the	above indicated tests.	Da	te / Ti Cust	me: <u>/</u>	/2//3	n rec	<u> </u>	lab?	~	Rece YES		by lal	b: NO	- Togla	Q_ NONE